A. N. CHOWDHARY, M.Sc.,
GEOLOGIST
Cell : 98454 73398

SRI SHIRDI SAI CONSULTANTS

.# 10, 3rd Floor, 19th Cross, 14th Main, Revenue Layout, Padamanabhanagar
Bangalore - 560 061.

GROUND WATER INVESTIGATION REPORT

S. No. : To the Asst. Executive Engineer Date :
BBMP
Dasarahalli Zone

1. Name of the Customer
2. a) Village Ward No:-12 Lakshmikar Layout b) Block / Taluk. c) District Bangalore
3. Location. Shivashankar house opp
4. Lithology of the Area Granetic Schists in nature
5. Tophographic Features of the Area The area was a plain land
6. Hydrogeological condition of the Area Good
7. Geophysical survey result. By Diving method
   a) Type of Method.
   b) No of Soundings Conducted.
   c) Recommended Sounding.
   d) Particulars of formations present in the subsurface/possible ground water zones encountered at
      340 - 360' ?
      500 - 540'
      780 - 830'
      } 2
      2
   e) Condition of Ground Water. Good
8. Type of well Recommended. Borewell (6½")
9. Depth Recommended. 850-900'
10. Expected Yield. 1500 - 1600 GPH
11. Quality of Water. Good
12. Approximate depth at which the water is expected to be met. Around 340' ?
13. Recommended Type and Length of casing to be inserted. nearly 260-280' of MS Casing may be needed
14. Rain water Harvesting adviced or not - Strikey Advised -

AE

Site Plan Map

Signature of the consultant

Note :- The Survey was carried out by this divining / Geophysical method of surveying is with our good knowledge and experience. However no guarantee of water will be given.

A. N. CHOWDHARY, M.Sc.,
GEOLOGIST
Cell : 98454 73398

SRI SHIRDI SAI CONSULTANTS

10, 3rd Floor, 19th Cross, 14th Main, Revenue Layout, Padamanabhanagar
Bangalore - 560 061.

GROUND WATER INVESTIGATION REPORT

S. No. : To the AEE Executive Engineer BBMP Dasarahalli Zone Date :

1. Name of the Customer
2. a) Village Ward No:- 12 Chikkagondanahalli b) Block / Taluk. c) District Bangalore
3. Location. Vani school road
4. Lithology of the Area Granetic Gneiss in nature
5. Tophographic Features of the Area The area was a plain area
6. Hydrogeological condition of the Area Good
7. Geophysical survey result. By Diving method
   a) Type of Method.
   b) No of Soundings Conducted.
   c) Recommended Sounding.
   d) Particulars of formations present in the subsurface/possible ground water zones encountered at
      Around 340' 530-560' 790-830' 2
   e) Condition of Ground Water. Good
8. Type of well Recommended. Bore well (6½")
9. Depth Recommended. 860-880'
10. Expected Yield. 1600-1800 GPH
11. Quality of Water. Good
12. Approximate depth at which the water is expected to be met. Around 340'
13. Recommended Type and Length of casing to be inserted. nearly 270-300' of Casing may be needed
14. Rain water Harvesting adviced or not - Strictly Adviced
15. Remarks.

Site Plan Map

Signature of the consultant

Note :- The Survey was carried out by this divining / Geophysical method of surveying is with our good knowledge and experience. However no guarantee of water will be given.

A. N. CHOWDHARY, M.Sc.,
GEOLOGIST
Cell : 98454 73398

SRI SHIRDI SAI CONSULTANTS

10, 3rd Floor, 19th Cross, 14th Main, Revenue Layout, Padamanabhanagar
Bangalore - 560 061.

GROUND WATER INVESTIGATION REPORT

S. No. : To the Asst Executive Engineer BBMP Dasarahalli Zone Date :

1. Name of the Customer
2. a) Village Ward No:-12 Saptha layout 1st cross near Babu house b) Block / Taluk. Attigere c) District Bangalore
3. Location.
4. Lithology of the Area Granetic (crystalline) in nature
5. Tophographic Features of the Area The area was a plain area
6. Hydrogeological condition of the Area Good
7. Geophysical survey result. By Diving method
   a) Type of Method.
   b) No of Soundings Conducted.
   c) Recommended Sounding.
   d) Particulars of formations present in the subsurface/possible ground water zones encountered at
      200 - 280'
      550 - 590'
      880 - 930'
   e) Condition of Ground Water. Good
8. Type of well Recommended. Bore well ($6\frac{1}{2}$")
9. Depth Recommended. 950 - 980'
10. Expected Yield. 1700 - 1800 GPH
11. Quality of Water. Good
12. Approximate depth at which the water is expected to be met. nearly 250 - 280' of MS
13. Recommended Type and Length of casing to be inserted. Casing may be needed
14. Rain water Harvesting adviced or not — Strictly Adviced —
15. Remarks.

AEE

ಸಹಾಯಕ ಕಾರ್ಯನಿರ್ವಾಹಕ ಅಭಿಯಂತರರು
ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ, ದಾಸರಹಳ್ಳಿ ವಲಯ
ಬ್ಯಾಡರಹಳ್ಳಿ ಬೆಂಗಳೂರು ನಗರಪಾಲಿಕೆ ಸಂಕೀರ್ಣ
ಎಸ್.ಎಂ ರಸ್ತೆ, ರವೀಂದ್ರನಗರ, ಬೆಂಗಳೂರು

Site Plan Map

Signature of the consultant

Note :- The Survey was carried out by this divining / Geophysical method of surveying is with our good knowledge and experience. However no guarantee of water will be given.

A. N. CHOWDHARY, M.Sc.,
GEOLOGIST
Cell : 98454 73398

SRI SHIRDI SAI CONSULTANTS

10, 3rd Floor, 19th Cross, 14th Main, Revenue Layout, Padamanabhanagar
Bangalore - 560 061.

GROUND WATER INVESTIGATION REPORT

S. No. : TO the Asst Executive Engineer Date :
BBMP
Dasarahalli Zone

1. Name of the Customer
2. a) Village Ward No: 12 b) Block / Taluk. c) District Bangalore
   Location. (Gidegonna Balaga) 6c main Road
3. Lithology of the Area Granetic / Schistose in nature
4. Tophographic Features of the Area The area was a plain land
5. Hydrogeological condition of the Area Good
6. Geophysical survey result. By Diving method
   a) Type of Method.
   b) No of Soundings Conducted.
   c) Recommended Sounding.
   d) Particulars of formations present in the subsurface/possible ground water zones encountered at
      350 - 380' } 2
      560 - 590' }
      810 - 860' }
   e) Condition of Ground Water. Good
7. Type of well Recommended. Borewell (6½")
8. Depth Recommended. 850 - 900'
9. Expected Yield. 1600 - 1800 GPH
10. Quality of Water. Good
11. Approximate depth at which the water is expected to be met. Around 350'
12. Recommended Type and Length of casing to be inserted. Nearly 260-300' of MS Casing may be needed
13. Rain water Harvesting adviced or not — Strictly Advised —
14. Remarks.

Site Plan Map

ACL
ಸಹಾಯಕ ಕಾರ್ಯನಿರ್ವಾಹಕ ಅಭಿಯಂತರರು
ಶೆಟ್ಟಿಹಳ್ಳಿ ಉಪವಿಭಾಗ, ದಾಸರಹಳ್ಳಿ ವಲಯ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಎಸ್.ಎಂ ರಸ್ತೆ, ರವೀಂದ್ರನಗರ, ಬೆಂಗಳೂರು

Signature of the consultant

Note :- The Survey was carried out by this divining / Geophysical method of surveying is with our good knowledge and experience. However no guarantee of water will be given.

PALLAVI BOREWELL & DRILLERS

Dealers in : 6½" 4½" Borewells Drilling & Inwell Drilling
All Kinds of Motors & Pumps, Sales & Service

No. 66/8, 1st Main Road, Maruthi Layout, M. G. Road,
Nelamangala Bangalore - 562 123.
Moble : 93412 24311, 90089 87530,



Ref : *Date :* .....

YIELD REPORT

1. Name and Address of the Party : AEE ward 12 shetty Lalli BBMP
2. Borewell Location : Chikkasandra vani school Road
3. Total Depth Drilled : 820 fts
4. Casing Pipe : 279 fts
5. Coupling : 23 nos
6. Yield Details :
   a) First Spring Touched at : 250 fts
   b) Second Spring Touched at : 470 fts
   c) Third Spring Touched at : 770 fts
7. Total Yield in G.P.H. : 1450 G.P.H
8. Remarks : yields good

AEE
ಸಹಾಯಕ ಕಾರ್ಯನಿರ್ವಾಹಕ ಅಭಿಯಂತರರು
ಶೆಟ್ಟಿಹಳ್ಳಿ ಉಪವಿಭಾಗ, ಯಶವಂತಪುರ ವಲಯ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಎಸ್.ಎಂ ರಸ್ತೆ, ರವೀಂದ್ರನಗರ, ಬೆಂಗಳೂರು

For **PALLAVI BOREWELL & DRILLERS**

M B Nirav Dalay
Proprietor

PALLAVI BOREWELL & DRILLERS

Dealers in : 6½" 4½" Borewells Drilling & Inwell Drilling
All Kinds of Motors & Pumps, Sales & Service
No. 66/8, 1st Main Road, Maruthi Layout, M. G. Road,
Nelamangala Bangalore - 562 123.
Moble : 93412 24311, 90089 87530,



Ref : *Date :* .....

YIELD REPORT

1. Name and Address of the Party : AEE ward 12 Shettyhalli BBMP
2. Borewell Location : Lakshmaiah layout Abbigere Shivshakar house opp 2nd cross
3. Total Depth Drilled : 820 fts
4. Casing Pipe : 279 fts
5. Coupling : 25 nos
6. Yield Details :
   a) First Spring Touched at : 300 fts
   b) Second Spring Touched at : 510 fts
   c) Third Spring Touched at : 790 fts
7. Total Yield in G.P.H. : 1400 G.P.H
8. Remarks : Yields good

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಶೆಟ್ಟಿಹಳ್ಳಿ ಉಪವಿಭಾಗ ಬಾಣಸವಾಡಿ ವಲಯ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಟಿಸ್.ಎಂ ರಸ್ತೆ, ರವೀಂದ್ರನಗರ, ಬೆಂಗಳೂರು

For PALLAVI BOREWELL & DRILLERS

M B Nirav Dalay

Proprietor

PALLAVI BOREWELL & DRILLERS

Dealers in : 6½" 4½" Borewells Drilling & Inwell Drilling
All Kinds of Motors & Pumps, Sales & Service

No. 66/8, 1st Main Road, Maruthi Layout, M. G. Road,
Nelamangala Bangalore - 562 123.
Moble : 93412 24311, 90089 87530,



Ref : *Date :* .....

YIELD REPORT

1. Name and Address of the Party : AEE ward 12 shettykalli BBMP
2. Borewell Location : Sapna layout Abbigere. 1st cross near babu house
3. Total Depth Drilled : 918.4 fts
4. Casing Pipe : 269 fts
5. Coupling : 22 nos
6. Yield Details :
   a) First Spring Touched at : 250 fts
   b) Second Spring Touched at : 560 fts
   c) Third Spring Touched at : 900 fts
7. Total Yield in G.P.H. : 1600 G.P.H
8. Remarks : yields good.

AE12
ಸಹಾಯಕ ಕಾರ್ಯನಿರ್ವಾಹಕ ಅಭಿಯಂತರರು
ಶೆಟ್ಟಿಹಳ್ಳಿ ಉಪವಿಭಾಗ, ಯಾರಬ್ಬಹಳ್ಳಿ ಪಟ್ಟಣ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಎಸ್.ಎಂ ರಸ್ತೆ, ರವೀಂದ್ರನಗರ, ಬೆಂಗಳೂರು

For PALLAVI BOREWELL & DRILLERS

M B Mruthyunjaya
Proprietor

PALLAVI BOREWELL & DRILLERS

Dealers in : 6½" 4½" Borewells Drilling & Inwell Drilling
All Kinds of Motors & Pumps, Sales & Service
No. 66/8, 1st Main Road, Maruthi Layout, M. G. Road,
Nelamangala Bangalore - 562 123.
Moble : 93412 24311, 90089 87530,



Ref : *Date : .....*

YIELD REPORT

1. Name and Address of the Party : AEE ward 12 Shettyhalli: BBMP
2. Borewell Location : Chikkasandra geleyara balaga 60 Feet Road
3. Total Depth Drilled : 820 feet
4. Casing Pipe : 302 fts
5. Coupling : 28 nos
6. Yield Details :
   a) First Spring Touched at : 325 fts
   b) Second Spring Touched at : 540 fts
   c) Third Spring Touched at : 800 fts
7. Total Yield in G.P.H. : 1500 G.P.H
8. Remarks : Yields good

AEE

ಸಹಾಯಕ ಕಾರ್ಯನಿರ್ವಾಹಕ ಅಭಿಯಂತರರು
ಶೆಟ್ಟಿಹಳ್ಳಿ ಉಪವಿಭಾಗ, ಬಾಪೂಜಿನಗರ ವಲಯ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಎಸ್.ಎಂ ರಸ್ತೆ, ರವೀಂದ್ರನಗರ, ಬೆಂಗಳೂರು

For PALLAVI BOREWELL & DRILLERS

M B Nirmal Raj

Proprietor